

**EuroLAB Automotive**

2550 McMillan Parkway Building C Suite 100
Fort Worth, TX 76137
(945) 402-3127
Eurolabsautomotive@gmail.com

RO #49

Service Advisor: Adrian Hernandez

Date Created: 04/03/26 at 08:26 AM CDT

Client: Mauricio Perez

Vehicle: 2014 Aston Martin Vanquish Base

2014 Aston Martin Vanquish Base 6.0L 12Cyl GAS Naturally Aspirated
VIN: SCFLDCFP9EGJ00489
License: WKC8212
Color: N/A
Odometer In: N/A / Out: N/A


RO # 49
Save Parts: No

Client concerns:

- Annual Service PPI, Replace buttons on the steering wheel. and check car

Inspection Rating Key:

😊 Checked & Okay ⚠ Requires Attention Soon ✖ Requires Immediate Attention — Not Applicable

Inspection		TECH: N/A
😊 ⚠ ✖ — Exterior		
✅ ☐ ☐ ☐ Head Lamps	Finding:	
✅ ☐ ☐ ☐ Tail Lamps	Finding:	
✅ ☐ ☐ ☐ Wiper Blades	Finding:	
☐ ✅ ☐ ☐ Paint Condition	Finding: A few minor scratches	
   		
✅ ☐ ☐ ☐ Dents	Finding:	
✅ ☐ ☐ ☐ Windshield Chips	Finding:	
😊 ⚠ ✖ — Interior		
☐ ☐ ✅ ☐ Warning Lights On	Finding: Trunk open warning light, Service Light, and Engine light Present	
☐ ☐ ☐ ✅ Cabin Air Filter	Finding:	
✅ ☐ ☐ ☐ A/C Cooling	Finding:	
✅ ☐ ☐ ☐ Window Operation	Finding:	
✅ ☐ ☐ ☐ Door Locks	Finding:	

☒ ☐ ☐ ☐ Seat Adjustment	Finding:
☐ ☐ ☐ ☒ Sunroof Operation	Finding:
☐ ☐ ☒ ☐ Other   	Finding: Driver seal on driver side is torn and we recommend replacing. Slight scuff on leather in the rear and scuff on door sill
☐ ☐ ☒ ☐ Underhood	
☒ ☐ ☐ ☐ Hood Shocks	Finding:
☐ ☒ ☐ ☐ Air Filter 	Finding: Air filters are dirty recommend replacing
☒ ☐ ☐ ☐ Drive Belts	Finding:
☐ ☒ ☐ ☐ Oil Leaks	Finding:
☒ ☐ ☐ ☐ Valve Cover Gasket	Finding:
☒ ☐ ☐ ☐ Radiator	Finding:
☒ ☐ ☐ ☐ Water Pump	Finding:
☒ ☐ ☐ ☐ Mounts	Finding:
☒ ☐ ☐ ☐ Fan Assembly	Finding:
☐ ☐ ☐ ☒ Other Items	Finding:
☐ ☐ ☒ ☐ Starting/Charging System	
☒ ☐ ☐ ☐ Battery	Finding:
☒ ☐ ☐ ☐ Battery Terminals	Finding:

☒ ☐ ☐ ☐ Starter	Finding:
☒ ☐ ☐ ☐ Alternator	Finding:
☐ ☐ ☐ ☒ Other Items	Finding:
☐ ☐ ☒ ☐ — Brakes	
☒ ☐ ☐ ☐ Front Brake Pads and Rotors	Finding:
☒ ☐ ☐ ☐ Rear Brake Pads and Rotors	Finding:
☒ ☐ ☐ ☐ Clean and Adjust	Finding:
☐ ☐ ☐ ☒ Other Items	Finding:
☐ ☐ ☒ ☐ — Steering and Suspension	
☒ ☐ ☐ ☐ Front Shocks/Struts	Finding:
☒ ☐ ☐ ☐ Rear Shocks/Struts	Finding:
☒ ☐ ☐ ☐ Front Axle	Finding:
☒ ☐ ☐ ☐ Rear Axle	Finding:
☒ ☐ ☐ ☐ Sway Bar Link	Finding:
☒ ☐ ☐ ☐ Wheel Bearing	Finding:
☒ ☐ ☐ ☐ Ball Joints	Finding:
☒ ☐ ☐ ☐ Tie Rods	Finding:
☒ ☐ ☐ ☐ Control Arms	Finding:
☒ ☐ ☐ ☐ Wheel Alignment	Finding:
☐ ☐ ☐ ☒ Other Items	Finding:
☐ ☐ ☒ ☐ — Under Vehicle	
☐ ☒ ☐ ☐ Oil Leaks	Finding: Fresh oil Found around the Oil filter and lower oil pan. Oil residue on side of engine block near oil fill cap, recommend performing oil change and cleaning the surrounding area. Check again after 500 miles.
☒ ☐ ☐ ☐ Coolant Leaks	Finding:
☒ ☐ ☐ ☐ Mounts	Finding:

☐ ☒ ☐ ☐ Other Damage



Finding: Exhaust valves were deleted with the aftermarket exhaust however the vacuum line was not plugged. Under trays and wheel well liners have minor damage. Not unusual for the mileage.

😊 ⚠️ ✖️ — Multipoint video

☐ ☐ ☐ ☐ Multi point video

Finding:

Multipoint Video

TECH: N/A

😊 ⚠️ ✖️ — Multipoint video

☐ ☐ ☐ ☐ Multi point inspection

Finding:

Multipoint Video

TECH: N/A

😊 ⚠️ ✖️ — Multipoint video

█
█
█
█
Multi point inspection

Finding:

